

M/0271008

Division of Oil, Gas, & Mining Mining Report		01/11/95	
MINE ID: M0270008		MINE NAME: SEVIER DRY LAKE PROJECT	
OPERATOR: CRYSTAL PEAK MINERALS CORP. CONTACT: MR. LARRY SOWER ADDRESS: PO BOX 10 C/O HIGH DESERT CONSULTIN MILFORD UT 84751 PHONE: (801)387-5542			
Surface Owner: BLM, ST Mineral Owner: BLM, ST		BLM #: U-37863-7912 Lease #:	
Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2
E2		NW	Sec 4 Town 24.0S Range 12.0W
Permit Status: APP		Mine Type [(S)urface, (U)nderground]: S	
Mine Status: REC		Acreage: 0	
Status Date: / /		Minerals Mined SALINES/POTASH	
DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED
03/07/86	08/06/86	08/27/87	03/04/94
BOND TYPE: SURETY/BOARD CONT		BOND AMOUNT: \$\$\$\$117,000	
ANNUAL REPORT YEAR: 94			
NONCOMP NOTICES:	YTD 0	Total 0	DATE ISSUED: / /
VIOLATIONS:	0	0	DATE ISSUED: / /
REVISIONS:	0	0	DATE REC'D: / /
AMENDMENTS:	0	0	DATE REC'D: / /
DATE RESOLVED: / /			
DATE RESOLVED: / /			
DATE APPROVED: / /			
DATE APPROVED: / /			
COMMENTS: 1993 REPORT STATED THAT RECLAMATION WAS COMPLETE. OPERATOR REQUESTED SURETY RELEASE IN 10/93. INSPECTION MADE SPRING OF '94 TO DETERMINE COMPLETENESS. EARTH WORK AT THE CAMP AREA WAS COMMENDABLE. THE MAIN DIKE WAS BREACHED NEAR THE LAKE SHORE LINE & AT THE INFLOW CANAL PUMP AREA. OPERATOR HAS BEEN ASKED TO DO ONE FINAL CLEANUP OF DEBRIS. \$2,000 BOND WILL HAVE TO BE LEFT IN PLACE FOR REVEGETATION STANDARDS.			